

CAMARO '93-'02

REPLACEMENT FOR

332-1546PTB-VC
CORNER LAMP
12PRS 2.91CFT

OEM PARTS
332-1546R/L-US



TUNING PARTS
332-1546PTB-VC



12V5W/12V27/7W
CLEAR

332-1546PXB-VC
332-1546PXB-2C
CORNER LAMP
12PRS 7.79CFT

TUNING PARTS
332-1546PXB-VC



12V5W/12V27/7W
CLEAR MR TYPE

332-1546PXB-2C



12V5W/12V27/7W
BLACK

CAMARO '98-'02

REPLACEMENT FOR

335-1122P-AS2
HEAD LAMP
3PRS 6.80CFT

OEM PARTS
335-1122R/L-AS



TUNING PARTS
335-1122P-AS2



BLACK

CAVALIER '91-'94

REPLACEMENT FOR

332-1513P-B-VC
CORNER LAMP
20PRS 3.01CFT

OEM PARTS
332-1513R/L-US



TUNING PARTS
332-1513P-B-VC



12V21W

CAVALIER '95-'99

REPLACEMENT FOR

332-1125PXUS
HEAD LAMP
3PRS 6.16CFT

OEM PARTS
332-1125R/L



TUNING PARTS
332-1125PXUS



9005/9006

332-1532PTB-VC
CORNER LAMP
20PRS 3.54CFT

OEM PARTS
332-1532R/L-U



TUNING PARTS
332-1532PTB-VC




CAVALIER '95-'99

REPLACEMENT FOR

332-1625PTB-C
FRONT LAMP
20PRS 2.49CFT

OEM PARTS
332-1625R/L-U-Y



TUNING PARTS
332-1625PTB-C



CAVALIER '00-'02

REPLACEMENT FOR

332-1580PTB-VC
CORNER LAMP
10PRS 5.63CFT

OEM PARTS
332-1580R/L-US



TUNING PARTS
332-1580PTB-VC

