



REPLACEMENT FOR

ATOS '98-'00



REPLACEMENT FOR

ATOS '01-'03



REPLACEMENT FOR

ATOS PRIME '04

HYUNDAI

221-1110-LD-E/EM 43T
 HEAD LAMP
 R 9210602010
 L 9210502010
 6PCS 5.58CFT



H4/PY21W/W5W

221-1124-LD-E/EM
 HEAD LAMP
 E: EM:
 R 92106-06000 R 92106-06000
 L 92101-06000 L 92105-06000
 6PCS 4.74CFT



H4/PY21W/W5W

221-1133-LD-EM
 HEAD LAMP
 R 92120-05520
 L 92110-05520
 4PCS 4.89CFT



H4/P21W/W5W

221-2002-AQ-y UQ '98-'99
 FOG LAMP
 R 92202-02000
 L 92201-02000
 12PCS 2.30CFT



H3

221-2003-UE
 FOG LAMP
 R 922020-2500
 L 922021-2500
 12PCS 2.960CFT



H3

221-2011-UE
 FOG LAMP
 R 92202-05500
 L 92201-05500
 12PCS 2.06CFT



GE881

221-2002-AQ-c UQ-c '00
 FOG LAMP
 R 92202-02100
 L 92201-02100
 12PCS 2.30CFT



H3

221-1401
 SIDE LAMP
 PCS CFT



TBA

221-1921-UE
 TAIL LAMP
 R 92402-05510
 L 92401-05510
 6PCS 3.86CFT



P21/5W/PY21W/W16W/P21/5W

221-1907
 TAIL LAMP
 R L
 PCS CFT



TBA

221-1906-UE
 TAIL LAMP
 R 92402-06000
 L 92401-06000
 6PCS 4.80CFT



P21W/P21W/P21/5W

221-1920-UE '2000
 TAIL LAMP
 R 92402-05100
 L 92401-05100
 R 92401-05110
 L 92402-05110
 6PCS 4.32CFT



P21W/P21W/P21/5W

