



REPLACEMENT FOR

REPLACEMENT FOR

REPLACEMENT FOR

HYUNDAI H100 PANEL VAN '93-'95 H100 PANEL VAN '96-'03 H100/PORTER II '04

221-1112-LD-E

HEAD LAMP
R 92102-43420
L 92101-43420
PCS CFT



H4/H1/W5W

TBA

221-1114-LD-E

HEAD LAMP
R 92102-43810
L 92101-43810
4PCS 4.20CFT



H4/H1/W5W

221-1135-LD-E

HEAD LAMP
R 92102-4F000
L 92101-4F000
R 92102-4F010
L 92101-4F010
PCS CFT



H4/1156/W5W

TBA

221-1511

CORNER LAMP
R 92302-43401
L 92301-43401
R 92302-43300
L 92301-43300
20PCS
3.20CFT



221-1513-AE/UE

CORNER LAMP
R 92302-43810
L 92301-43810
20PCS 3.20CFT



PY21W/W5W

221-1135-LD-EM

HEAD LAMP
R 92120-4F030
L 92110-4F030
PCS CFT



H4/1156/W5W

TBA

221-1901

TAIL LAMP
R 92402-43300
L 92401-43300
PCS CFT



TBA

221-1902-AE/UE

TAIL LAMP
R 92402-43800
L 92401-43810
10PCS 4.07CFT

