








	<p style="text-align: center;">1001M</p> <p>REPLACES</p> <p>SEAT 6N0 905 104, 867 905 352, 867 905 104</p> <p>SKODA 004 050 016, 6N0 905 104</p> <p>VW 6N0 905 104, 867 905 352 867 905 104, 867 905 104A, 357 905 104</p> <p>AUDI 867 905 104, 867 905 104A, 867 905 352</p> <p>BOSCH 0 221 601 003, 0 221 601 004, 0 221 601 005 0 986 221 000</p>
	<p style="text-align: center;">1002</p> <p>REPLACES</p> <p>HONDA 30510-P73-A01, 30510-P73-A02 30510-PT2-006, 30500-PT2-006 30520-PT2-006</p> <p>ROVER GCL195, NEC100530</p> <p>BOSCH F 000 ZS0 116</p> <p>HITACHI TC-08A</p>
	<p style="text-align: center;">1003</p> <p>REPLACES</p> <p>CHRYSLER 4751253, 4797293</p> <p>DODGE 5234210, 5234610, 5252577</p> <p>PLYMOUTH 19017110</p>
	<p style="text-align: center;">1004</p> <p>REPLACES</p> <p>SUZUKI 330 900 115A</p> <p>VW 330 905 115A</p> <p>BOSCH 0 221 502 007, 0 221 502 008</p>
	<p style="text-align: center;">1005</p> <p>REPLACES</p> <p>DAIHATSU 19080-87703, 19080-Z9121 100297-0860</p> <p>DIAMOND F-718</p>

	<p style="text-align: center;">1006</p> <p>REPLACES DAIHATSU 90048-52056, 90048-52096 90048-52091 DIAMOND F-076, F-614</p>
	<p style="text-align: center;">1007</p> <p>REPLACES DAIHATSU 90048-52109 DIAMOND F-714</p>
	<p style="text-align: center;">1008</p> <p>REPLACES CITROEN 597045, 96035284 PEUGEOT 597045, 96035284 BOSCH 0 986 221 029</p>
	<p style="text-align: center;">1009</p> <p>REPLACES CITROEN 597047, 96041378 FIAT 9604137880 PEUGEOT 597047, 96041378</p>
	<p style="text-align: center;">1010</p> <p>REPLACES CITROEN 597043, 96010513, 97530780 PEUGEOT 597043 BOSCH F 000 ZS0 114</p>

	<p style="text-align: center;">1011</p> <p>REPLACES CITROEN 597042, 97531206 PEUGEOT 597042, 97531206 BOSCH F 000 ZS0 113</p>
	<p style="text-align: center;">1012</p> <p>REPLACES FIAT/LANCIA 7746154, 7746152, 7698431 7663177, 7582152 BOSCH 0 986 221 027</p>
	<p style="text-align: center;">1013</p> <p>REPLACES FORD 1953302, 1953306, F3XA-12029-AA F3XY-12029-A, F5XZ-12029-AA NISSAN 22433-55S10, 22433-56E11, 22433-0B00 22433-0B000, 22433-0B001, 22433-0B010 22433-51J10, 22433-53J20, 22433-56E12 22448-0C801, 22448-0C802, 22448-D4000</p>
	<p style="text-align: center;">1014</p> <p>REPLACES HONDA 30500-POH-A01, 30500-PAA-A01 30500-PCA-003, 30500-PDA-E01 30500-POA-A01 HITACHI CMIT-228</p>
	<p style="text-align: center;">1015</p> <p>REPLACES SEAT 6N0 905 104, 867 905 352, 867 905 104 SKODA 004 050 016, 6N0 905 104 VW 6N0 905 104, 867 905 352 867 905 104, 867 905 104A, 357 905 104 AUDI 867 905 104, 867 905 104A, 867 905 352 BOSCH 0 221 601 003, 0 221 601 004, 0 221 601 005 0 986 221 000</p>

	<p style="text-align: center;">1016</p> <p>REPLACES</p> <p>TOYOTA 90919-02164</p> <p>GM 94404545, 94853695, 88921431</p> <p>ISUZU 8-94404-545-0</p> <p>DENSO 029700-6310</p> <p>BOSCH F000ZS0117</p>
	<p style="text-align: center;">1017</p> <p>REPLACES</p> <p>TOYOTA 90919-02208, 19500-74040, 19500-74050 90919-02197, 19080-13030</p> <p>DAIHATSU 90080-19004</p> <p>DENSO 029700-7690</p>
	<p style="text-align: center;">1018</p> <p>REPLACES</p> <p>MAZDA FTM558A3, G601-18-100X</p>
	<p style="text-align: center;">1019</p> <p>REPLACES</p> <p>mitsubishi MD339027</p> <p>DIAMOND F-809</p>
	<p style="text-align: center;">1020</p> <p>REPLACES</p> <p>mitsubishi MD309455, V31</p>

	<p style="text-align: center;">1021</p> <p>REPLACES MITSUBISHI MD309456</p>
	<p style="text-align: center;">1022</p> <p>REPLACES MITSUBISHI MD338169, 4G63, 4G64</p>

EXPERTISE LEAD EXCELLENCE
TEMCO

	<p style="text-align: center;">2001M</p> <p>REPLACES NISSAN 22448-4M500, 22448-4M50A HITACHI CM11-205</p>
	<p style="text-align: center;">2002M</p> <p>REPLACES VW 06B 905 105, 06B 905 115 06B 905 115B, 06B 905 115E</p>
	<p style="text-align: center;">2003</p> <p>REPLACES SUZUKI 33410-77E11, 33410-77E10 BOSCH 0986 JG1010</p>
	<p style="text-align: center;">2004M</p> <p>REPLACES VW 06A 905 115, 06A 905 115A, 06A 905 115C 06B 905 115G, 06B 905 115H, 06B 905 115J 06B 905 115M, 06B 905 115L, 06B 905 115N 06B 905 115Q, 06B 905 115R, 06C 905 115F 06C 905 115A, 06B 905 115D, 06C 905 115L 06C 905 115K, 06C 905 115H, 06C 905 115G BOSCH 0 986 221 024</p>
	<p style="text-align: center;">2005M</p> <p>REPLACES VW 036 905 100A, 036 905 100B, 036 905 100 036 905 100C, 036 905 100D 036 905 715, 036 905 715A, 036 905 715F 036 905 715C, 036 905 715E BOSCH 0 986 221 023</p>

	<p style="text-align: center;">2006M</p> <p>REPLACES HYUNDAI/KIA 27300-39800, 27301-39800</p>
	<p style="text-align: center;">2007M</p> <p>REPLACES SUZUKI 33400-65G00, 33400-65G01, 33400-65G02 33410-65G00, 33410-77E01, 9C19-0370</p>
	<p style="text-align: center;">2008</p> <p>REPLACES REFINE 1026102GAA</p>
	<p style="text-align: center;">2009</p> <p>REPLACES OPEL 1208306, 90532618, 90543059 BOSCH 0 221 503 014</p>
	<p style="text-align: center;">2010</p> <p>REPLACES HYUNDAI 27300-85010, 10E2702 DENSO 65Z9003-6002</p>

	<p style="text-align: center;">2011M</p> <p>REPLACES MITSUBISHI MD325048, CW723219, MD360384</p>
	<p style="text-align: center;">2012M</p> <p>REPLACES SUZUKI 33400-65G00, 33400-65G01</p>
	<p style="text-align: center;">2013M</p> <p>REPLACES MITSUBISHI CW724632</p>
	<p style="text-align: center;">2014M</p> <p>REPLACES MITSUBISHI MD363552 HITACHI A4H7C01671</p>
	<p style="text-align: center;">2015M</p> <p>REPLACES SUZUKI 33410-77E21, 33410-77E22, 33410-77E20</p>

	<p style="text-align: center;">2016M</p> <p>REPLACES</p> <p>NISSAN 22448-31U00, 22448-31U01, 22448-31U11 22448-31U10</p> <p>HITACHI H6T10171A</p>
	<p style="text-align: center;">2017M</p> <p>REPLACES</p> <p>NISSAN 22448-31U06, 22448-31U16 22448-31U15, 22448-31U05</p> <p>HITACHI H6T10271A, H6T10271A</p>
	<p style="text-align: center;">2018M</p> <p>REPLACES</p> <p>NISSAN 22448-2Y000, 22448-2Y001, 22448-2Y010</p>
	<p style="text-align: center;">2019M</p> <p>REPLACES</p> <p>NISSAN 22448-2Y005, 22448-2Y015, 22448-2Y007 22448-2Y006, 22448-AL510</p>
	<p style="text-align: center;">2020M</p> <p>REPLACES</p> <p>MITSUBISHI MD325052, CW723220</p> <p>HITACHI H6T20171</p>

	<p style="text-align: center;">2021M</p> <p>REPLACES</p> <p>MAZDA ZZY1-18-100, ZL01-18-100A, ZL01-18-100B ZL01-18-100, BP6D-18-100A, ZLY1-18-100</p> <p>FORD F0TZ-12029-A</p> <p>BOSCH F 005 X11 773</p>
	<p style="text-align: center;">2022M</p> <p>REPLACES</p> <p>FORD FP85-18-100, FP85-18-100C, FFY1-18-100</p>
	<p style="text-align: center;">2023M</p> <p>REPLACES</p> <p>TOYOTA 90919-T2002, 90919-02239, 90080-19015 90080-19019, 90080-19017, 90919-02262 90919-19019</p> <p>CITROEN/PEUGEOT 597088</p> <p>GM 94859441</p>
	<p style="text-align: center;">2024M</p> <p>REPLACES</p> <p>TOYOTA 90919-02244, 90080-19023, 90919-02266</p>
	<p style="text-align: center;">2025M</p> <p>REPLACES</p> <p>HYUNDAI 27301-38020</p> <p>BOSCH 0 986 221 018</p>

	<p style="text-align: center;">2026M</p> <p>REPLACES HONDA 30520-PGK-A01, 30520-PVF-A01, 30520-P8E-A01 30520-P8F-A01, 30520-P8F-A02, 30520-PVJ-A01 30520-P8E-A00, 30520-RCA-A02, 30520-RDJ-A01 30520-PVK-A01, 30520-RCA-A01, 30520-PVK-A01 DENSO 099700-061, 099700-072</p>
	<p style="text-align: center;">2027</p> <p>REPLACES BMW 12 13 1 712 219, 12 13 1 712 223 12 13 1 551 260 BOSCH 0 221 504 464, 0 221 504 100 PEUGEOT 3008</p>
	<p style="text-align: center;">2028M</p> <p>REPLACES NISSAN 22448-8H315, 22448-8H300, 22448-8H310 22448-8H311, 22433-8H315</p>
	<p style="text-align: center;">2029M</p> <p>REPLACES NISSAN 22448-8J115, 22448-8J111, 22433-8J115 22448-8J11C, 22448-8J110, 22448-8J100 AIC-3116</p>
	<p style="text-align: center;">2030M</p> <p>REPLACES MITSUBISHI MD362907, CW747273, MD362903 CHRYSLER MD362907, MD326903 BOSCH 0221 503 465</p>

	<p style="text-align: center;">2031M</p> <p>REPLACES MITSUBISHI MD361710 DENSO 099700-048</p>
	<p style="text-align: center;">2032M</p> <p>REPLACES MITSUBISHI MD362903</p>
	<p style="text-align: center;">2033M</p> <p>REPLACES TOYOTA 90919-02230, 90080-19027, 90919-02249 90919-02259 GM 88921392</p>
	<p style="text-align: center;">2034</p> <p>REPLACES FORD 6485688, 91XF-12029-AA, 91XF-12029-BA BOSCH 0 221 505 423</p>
	<p style="text-align: center;">2035</p> <p>REPLACES RENAULT 7700875000, 8200208611, 8200380267 8200145186, 7700113357, 7700107177 8200405098 NISSAN 22448-00QAA, 22448-6N011 OPEL 4408389, 91159996, 4432202, 4408283 4413233</p>

	<p style="text-align: center;">2036M</p> <p>REPLACES VOLVO 30713417, 8677837 BOSCH 0 221 604 010</p>
	<p style="text-align: center;">2037M</p> <p>REPLACES VOLVO 30713416, 9125601, 91256010, 91256016 BOSCH 0 221 604 008, 0 221 604 001</p>
	<p style="text-align: center;">2038M</p> <p>REPLACES MAZDA ZM01-18-100, BP60-18-100A GM 976330, 976343, 976373</p>
	<p style="text-align: center;">2039</p> <p>REPLACES FORD 4M5G-12A366-BC, 4M5G-12A366-BB 4M5G-12A366-BA, 4M5Z-12029-BC 4M5Z-12029-BA, 4M5Z-12029-A, 4M5Z-12029B 1224925, 1322402, 1314271, 30711786, DG507 MAZDA LF16-18-100B, LF16-18-100A, ZZCA-18-100</p>
	<p style="text-align: center;">2040M</p> <p>REPLACES TOYOTA 90919-02240, 90080-19021, 90919-T2003 90919-02265</p>

	<p style="text-align: center;">2041</p> <p>REPLACES</p> <p>FORD 1L8Z-12029-AB, 1L8E-12A366-AB, 1L8U-12A366-AA XS2U-12A388-AA, XS2Z-12029-AA, 1L8Z-12029-AA 1L8E-12A366-AC, 1L8E-12A366-AB, 1L8E-12A366-AA 9L8E-12A366-AA, 9C040319</p> <p>MAZDA 1LZ1-18-100, AJ03-18-100, AJ09-18-100 AJ51-18-100A, DG513</p>
	<p style="text-align: center;">2042</p> <p>REPLACES</p> <p>FORD F7TZ-12029-AB, F7TZ-12029-BA F7TZ-12029-CA, F7TZ-12029-CC 1L2U-12029-AA, 1L2Z-12029-AA F7TZ-12A366-BA, F7TU-12A366-AB 3W7E-12A366-AA, 3W7Z-12029-AA DG508, 88921369, DG457, DG472, DG491</p>
	<p style="text-align: center;">2043M</p> <p>REPLACES</p> <p>NISSAN 22448-6N000, 22448-6N002, 22448-6N010 22448-6N012, 22448-6N015, 22448-6N011</p>
	<p style="text-align: center;">2044M</p> <p>REPLACES</p> <p>NISSAN 22448-AL615, 22433-AL615</p>
	<p style="text-align: center;">2045M</p> <p>REPLACES</p> <p>MITSUBISHI MD362907 CHRYSLER MD362907</p>

	<p style="text-align: center;">2046M</p> <p>REPLACES NISSAN 22448-7S015, 22448-AR215, 22433-AR215 22448-AR210, AIC-4002G</p>
	<p style="text-align: center;">2047M</p> <p>REPLACES HYUNDAI/KIA 27300-39050, 27300-39000</p>
	<p style="text-align: center;">2048M</p> <p>REPLACES SUZUKI 33410-66D10, 33410-66D00, 33410-66D01 CHEVROLET 30020581 HYUNDAI 88921408 MISUBISHI JL474Q</p>
	<p style="text-align: center;">2049M</p> <p>REPLACES HONDA 30520-PNA-007, 30520-RRA-007, 30520-RAA-007 30520-PMA-007 DENSO 099700-070, 099700-116</p>
	<p style="text-align: center;">2050M</p> <p>REPLACES TOYOTA 90919-02234, 90080-19016, E507C GM 88921393</p>

	<p style="text-align: center;">2051</p> <p>REPLACES RENAULT/NISSAN</p>
	<p style="text-align: center;">2052</p> <p>REPLACES RENAULT/NISSAN</p>
	<p style="text-align: center;">2053M</p> <p>REPLACES MITSUBISHI MR994643, MD994643, MR994642</p>
	<p style="text-align: center;">2054M</p> <p>REPLACES SUZUKI 33400-75F10, 33400-76G1, 33400-51K40 DENSO 90048-86080</p>
	<p style="text-align: center;">2055M</p> <p>REPLACES HONDA 30521-PWA-003, 30521-REA-Z01, 30521-PWA-S01 HITACHI CM11-108</p>

	<p style="text-align: center;">2056M</p> <p>REPLACES HONDA 30520-PWC-003, 30520-REB-Z01, 30520-PWC-S01 HITACHI CM11-110</p>
	<p style="text-align: center;">2057M</p> <p>REPLACES HONDA 30520-PWA-003, 30520-REA-Z01, 30520-PWA-S01 HITACHI CM11-109</p>
	<p style="text-align: center;">2058</p> <p>REPLACES HYUNDAI 27301-23400, BAE400D</p>
	<p style="text-align: center;">2059</p> <p>REPLACES HYUNDAI 27301-37410</p>
	<p style="text-align: center;">2060</p> <p>REPLACES CHRYSLER 4609088AC, 4609088AD, 4609088AF 4609088AE, 4609088AG, 4609088AH GM 88921394</p>

	<p style="text-align: center;">2061</p> <p>REPLACES</p> <p>BENZ 000 158 72 03, 0001594142</p> <p>BOSCH 0 221 504 001</p>
	<p style="text-align: center;">2062M</p> <p>REPLACES</p> <p>VW/SEAT 022 905 100G, 022 905 100K, 022 905 100A 022 905 100N, 022 905 100D, 022 905 715C</p> <p>FORD 1331283, 1120169, 1673468, 1252407, 1362718 6M21-12029-AA, YM21-12029-AC</p> <p>LUCAS DMB910</p>
	<p style="text-align: center;">2063M</p> <p>REPLACES</p> <p>MAZDA N3H1-18-100, N3H1-18-1009U, N3H1-18-100A9U N3H1-18-100B9U, N3H1-18-100A, N3H1-18-100B</p>
	<p style="text-align: center;">2064M</p> <p>REPLACES</p> <p>NISSAN 22448-ED800, 22448-ED800 EP, 22448-CJ00A</p> <p>BOSCH 0 221 604 014, 0 221 604 020</p>
	<p style="text-align: center;">2065M</p> <p>REPLACES</p> <p>SUBARU 22433-AA540, 22433-AA418, 22448-AA430 22433-AA480, 22433-AA640, 22433-AA460</p>

	<p style="text-align: center;">2066</p> <p>REPLACES CHRYSLER 4609095AC, 4609095AD, 4609095AE 4609095AF, 4609095AG, 4609095AB 4609095AI, 1208210, 90584337 GM 88921395</p>
	<p style="text-align: center;">2067M</p> <p>REPLACES VW 07C 905 115D, 07C 905 115J, 07C 905 115H 07C 905 115F, 07C 905 115E, 07C 905 115C 07C 905 715</p>
	<p style="text-align: center;">2068M</p> <p>REPLACES AUDI 077 905 115Q, 077 905 115K, 077 905 115H 077 905 115F, 077 905 115E, 077 905 115C 077 905 115T</p>
	<p style="text-align: center;">2069M</p> <p>REPLACES TOYOTA 90919-02229</p>
	<p style="text-align: center;">2070M</p> <p>REPLACES TOYOTA 90919-522F1</p>

	<p style="text-align: center;">2071M</p> <p>REPLACES TOYOTA 90919-A2002 , 90919-02251, 90919-02255 90919-A2004, 90919-A2007</p>
	<p style="text-align: center;">2072M</p> <p>REPLACES TOYOTA 90919-02250 , 90919-A2003, 90919-02256 90919-A2005, 90919-T2004, 90919-C2001 90919-C2004, 90919-02257</p>
	<p style="text-align: center;">2073M</p> <p>REPLACES TOYOTA 90919-02238 GM 88970216</p>
	<p style="text-align: center;">2074M</p> <p>REPLACES TOYOTA 90919-02248, 90919-02247, 90919-A2001 90919-T2001, 90919-C2002, 90919-02260 90919-A2006 GM 89057998</p>
	<p style="text-align: center;">2075M</p> <p>REPLACES TOYOTA 90919-02243</p>

	<p style="text-align: center;">2076M</p> <p>REPLACES TOYOTA 90919-02235</p>
	<p style="text-align: center;">2077</p> <p>REPLACES CHRYSLER 04606869AB, 04606869AA</p>
	<p style="text-align: center;">2078M</p> <p>REPLACES HONDA 30520-RNA-A01 DENSO 099700-101</p>
	<p style="text-align: center;">2079M</p> <p>REPLACES OPEL 12583514 , 12566569, 12613057, 12613051 GMC 12629037 HOLDEN 12566569 BOSCH 0 221 604 104, 0 221 604 112</p>
	<p style="text-align: center;">2080</p> <p>REPLACES TOYOTA 90919-02214, 90919-02211</p>

	<p style="text-align: center;">2081M</p> <p>REPLACES NISSAN 22448-4W011, 22448-4W010</p>
	<p style="text-align: center;">2082</p> <p>REPLACES KIA 27301-26640</p>
	<p style="text-align: center;">2083M</p> <p>REPLACES SUZUKI 33400-65J00, 33410-65J00 HITACHI H6T11371</p>
	<p style="text-align: center;">2084</p> <p>REPLACES VOLVO 1275602, MB029700-8180, 12756020 12756029, 30875593</p>
	<p style="text-align: center;">2085M</p> <p>REPLACES SUBARU 22433-AA550, 22433-AA451</p>

	<p style="text-align: center;">2086M</p> <p>REPLACES HONDA 30520-P8E-A01, 30520-RCA-A02, 30520-RCA-A01 30520-P8E-S01, 30520-P8F-A01 HITACHI CM11-207A</p>
	<p style="text-align: center;">2087M</p> <p>REPLACES HONDA 30520-R40-007 DENSO 099700-147</p>
	<p style="text-align: center;">2088M</p> <p>REPLACES HONDA 30520-RNO-A01</p>
	<p style="text-align: center;">2089M</p> <p>REPLACES HONDA 30520-PHM-003 HITACHI CM11-106</p>
	<p style="text-align: center;">2090M</p> <p>REPLACES HONDA 30520-RBO-003, 30520-RBO-S01 HITACHI CM11-116</p>


	<p style="text-align: center;">2091M</p> <p>REPLACES MITSUBISHI 33400-62J00, 33400-62J01, 33400-83E01</p>
	<p style="text-align: center;">2092M</p> <p>REPLACES NISSAN 22448-3H000, 22448-6P000 GM 88921362</p>
	<p style="text-align: center;">2093M</p> <p>REPLACES TOYOTA 90080-19025, 90919-02246</p>
	<p style="text-align: center;">2094</p> <p>REPLACES FORD 3R2U-12A366-AB, BA12A366-A, BAF12A366-A</p>
	<p style="text-align: center;">2095M</p> <p>REPLACES BUICK 12618542, 12590990, 12610626, 12632479, 1208087 MITSUBISHI 33400-78J00, 33400-78J01, 33400-78J02 DENSO 099700-1180, 099700-1510, 099700-1550</p>

	<p style="text-align: center;">2096M</p> <p>REPLACES FIAT 46794782 BOSCH 0221 604 103</p>
	<p style="text-align: center;">2097M</p> <p>REPLACES ISUZU 8-97136-325-0, 8-97136-554-0, 8-97174-554-0 HITACHI CM11-102</p>
	<p style="text-align: center;">2098M</p> <p>REPLACES TOYOTA 19500-B0010, 19070-B0010</p>
	<p style="text-align: center;">2099</p> <p>REPLACES KIA 27300-3F100</p>
	<p style="text-align: center;">2100M</p> <p>REPLACES TOYOTA 90919-A2004, 90919-02255</p>

	<p style="text-align: center;">2101</p> <p>REPLACES FORD F5XZ-12029-AA, F6DZ-12029-AA F6DZ-12029-EA, F6DU-12A366-AB</p>
	<p style="text-align: center;">2102</p> <p>REPLACES VOLVO 3531300, 1275971</p>
	<p style="text-align: center;">2103M</p> <p>REPLACES GM 55584745, 55571790, 55561655, 96476983 DELPHI 28326923</p>
	<p style="text-align: center;">2104M</p> <p>REPLACES TOYOTA 90919-C2003, 90919-02252, 90919-02258 90919-C2005 GM 94859442</p>
	<p style="text-align: center;">2105M</p> <p>REPLACES DAIHATSU 90048-52126, 099700-0570</p>

	<p style="text-align: center;">2106M</p> <p>REPLACES TOYOTA 19070-BZ040, 19070-BZ060 DENSO 099700-0990, 099700-0991</p>
	<p style="text-align: center;">2107</p> <p>REPLACES PEUGEOT/CITROEN 597080, 96363378 SAGEM 9636337880, 2526182A VALEO 245095, 96363378 PEUGEOT 307 1.6L</p>
	<p style="text-align: center;">2108M</p> <p>REPLACES TOYOTA 90919-02237</p>
	<p style="text-align: center;">2109M</p> <p>REPLACES NISSAN 22448-4W001, 22448-4W000</p>
	<p style="text-align: center;">2110M</p> <p>REPLACES NISSAN 22448-JA00C, 22448-ED000, 22448-JA00A 22448-EA000, 22448-1HC0A, 22448-1HM0A</p>

	<p style="text-align: center;">2111M</p> <p>REPLACES NISSAN 22448-JA10C, 22448-JA10A, 22448-JN10A</p>
	<p style="text-align: center;">2112</p> <p>REPLACES DAEWOO 96415010</p>
	<p style="text-align: center;">2113</p> <p>REPLACES OEM J5700-3705060A 适用：玉柴发动机</p>
	<p style="text-align: center;">2114</p> <p>REPLACES OEM 37.5D-05010 适用：NQ系列天然气发动机</p>
	<p style="text-align: center;">2115</p> <p>REPLACES BOSCH F01R00A013</p>

	<p style="text-align: center;">2116M</p> <p>REPLACES BUICK 12578224, 12629646, 12589623, 12638824 15230829 DENSO 099700-0850, 099700-1990</p>
	<p style="text-align: center;">2117</p> <p>REPLACES FORD 3L3E-12A366-CA, 3L3Z-12029-BA 3L3U-12A366-BB, DG511, FD508</p>
	<p style="text-align: center;">2118</p> <p>REPLACES ROEWE NEC90012A ROVER NEC000120, NEC000120L, NEC100730 BERU 0040 100 501 0000</p>
	<p style="text-align: center;">2119M</p> <p>REPLACES MAZDA LFB6-18-100, LFB6-18-100C LFB6-18-100A, LFB6-18-100B</p>
	<p style="text-align: center;">2120</p> <p>REPLACES ROVER NEC000130, NEC100870 BERU 0040 100 502 0000</p>



	<p style="text-align: center;">2121M</p> <p>REPLACES</p> <p>MAZDA L3G2-18-100, L3G2-18-100B, L3G2-18-100A</p> <p>FORD 6M8G-12A366</p>
	<p style="text-align: center;">2122</p> <p>REPLACES</p> <p>TOYOTA 90919-02212</p> <p>DENSO 0297007951</p> <p>GM 8687939</p>
	<p style="text-align: center;">2123</p> <p>REPLACES</p> <p>TOYOTA 90919-02213</p> <p>DENSO 0297007941</p> <p>GM 88921357</p>
	<p style="text-align: center;">2124</p> <p>REPLACES</p> <p>KIA OK247-18-100A</p>
	<p style="text-align: center;">2125</p> <p>REPLACES</p> <p>KIA OK013-18-100</p> <p>GM 88921371</p>

	<p style="text-align: center;">2126M</p> <p>REPLACES GM 12568062, 71760623 ISUZU 8-12568-062-0</p>
	<p style="text-align: center;">2127</p> <p>REPLACES KIA/HYUNDAI 27301-3C000, 27301-3C010</p>
	<p style="text-align: center;">2128</p> <p>REPLACES CHRYSLER 56028138AB, 56028138AD, 56028138AF 56028138AE, 56028138, 56028138BA</p>
	<p style="text-align: center;">2129</p> <p>REPLACES GM 55570160, 55585539, 96476979 DELPHI 28125877, 28326925</p>
	<p style="text-align: center;">2130M</p> <p>REPLACES MAZDA ZJ20-18-100, ZJ20-18-100A, ZJ20-18-100B ZJ49-18-100</p>

	<p style="text-align: center;">2131M</p> <p>REPLACES MAZDA ZJ01-18-100, AIC-4051</p>
	<p style="text-align: center;">2132</p> <p>REPLACES CHRYSLER 04606824AB, 04606824AC</p>
	<p style="text-align: center;">2133M</p> <p>REPLACES MITSUBISHI H6T60271, 12787707</p>
	<p style="text-align: center;">2134M</p> <p>REPLACES MITSUBISHI H6T15171, 12584368</p>
	<p style="text-align: center;">2135</p> <p>REPLACES LOTUS PW812018, A2C53283938</p>

	<p style="text-align: center;">2136</p> <p>REPLACES LOTUS PW812712</p>
	<p style="text-align: center;">2137</p> <p>REPLACES KAI OK2A3-18-100A</p>
	<p style="text-align: center;">2138M</p> <p>REPLACES SUBARU 22433-AA531, 22433-AA411</p>
	<p style="text-align: center;">2139M</p> <p>REPLACES SUBARU 22433-AA600, 22433-AA601</p>
	<p style="text-align: center;">2140M</p> <p>REPLACES SUBARU 22433-AA610, 22433-AA612</p>

	<p style="text-align: center;">2141</p> <p>REPLACES FORD 6E5G12A366AD, 6E5G12A366AE 6E5Z12029AA, 6E5G12A366CA</p>
	<p style="text-align: center;">2142</p> <p>REPLACES TOYOTA 90919-02205</p>
	<p style="text-align: center;">2143</p> <p>REPLACES FORD 9E5Z-12029-A , DG-522 MAZDA L507-18-100</p>
	<p style="text-align: center;">2144M</p> <p>REPLACES SUBARU 22433-AA421, 22433-AA560</p>
	<p style="text-align: center;">2145</p> <p>REPLACES TOYOTA 90919-02215, 90080-19012 GM 88921336</p>

	<p style="text-align: center;">2146M</p> <p>REPLACES NISSAN 22448-FY500</p>
	<p style="text-align: center;">2147M</p> <p>REPLACES VW 04E 905 110, 04E 905 110A, 04E 905 110B 04E 905 110C, 04C 905 110D, 04C 905 110D</p>

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco

EXPERTISE LEAD EXCELLENCE

Temco


	<p style="text-align: center;">3001</p> <p>REPLACES GM D524, D531, D536 1876209, 1985474, 1988908</p>
	<p style="text-align: center;">3002</p> <p>REPLACES GM D530, D523, D532, 8131936, J8131936, 1875894 1985473, 10497132, 1694925-C1, 10497133 CONP12029A, DGG-419</p>
	<p style="text-align: center;">3003</p> <p>REPLACES FORD E1EF-12029-AA, E2EF-12029-AA, E2FZ-12029-A E3EF-12029-AA, E3EZ-12029-A, E73F-12029-AA E73F-12029-AB, E73Z-12029-A, E32Z-12029-A 1694979-C1, F515-18-10X, FS15-18-10X 12321405, 12336833, 19017194, F-503, F-1953 DG-325, DG-325A, DGE-325ADP, DG-434, DGE-453 F7PZ-12029-AA</p>
	<p style="text-align: center;">3004</p> <p>REPLACES GM D525, D527, D528, D529, 1187847, 8134003 J8134003, 1115444, 1115445, 1115447, 1115448 1115455, DGG-222, DGG-322, DGG-421, 5-73, 5-74</p>
	<p style="text-align: center;">3005</p> <p>REPLACES GM D535, D537, D544, D575, D573, DR37X, 1115315 1115468, 1106013, 10477944, 1115316, 1115317 ISUZU 8-01115-315-0, 8-01115-466-0 DIAMOND F-616 AMC 8983501871</p>





	<p style="text-align: center;">3006</p> <p>REPLACES</p> <p>GM D535, D537, D544, D560, D573 1115315, 1115466, 1115468, 1115317 1115491, 10477208, 83501871</p> <p>ISUZU 8-01115-315-0, 8-01115-466-0 806673T, 817378T</p>
	<p style="text-align: center;">3007</p> <p>REPLACES</p> <p>GM 1115467, 8A09</p>
	<p style="text-align: center;">3008</p> <p>REPLACES</p> <p>GM D535, D537, D544, D560, D573 1115315, 1115466, 1115468, 1115317 1115491, 10477208, 83501871</p> <p>ISUZU 8-01115-315-0, 8-01115-466-0 806673T, 817378T</p>
	<p>REPLACES</p>

	<p style="text-align: center;">4001</p> <p>REPLACES ALFA ROMEO 60805420, 60809492, 060708038 FIAT 46543562, 46548037, 46790073 7626232, 7672018, 7692473</p>
	<p style="text-align: center;">4002</p> <p>REPLACES ISUZU 8-10468-391-0, D555 HOLDEN 10 468 391, 10 472 401, 10 477 602, 1103744 10 467 067, 1103646, 1103662, 1103663, 1103608 BOSCH F 005 X10 588</p>
	<p style="text-align: center;">4003</p> <p>REPLACES MITSUBISHI MD184230, MD334558, MD152648 MD346835 DIAMOND F-608, F-648, 27310-37100 BOSCH 0 986 JG1 002</p>
	<p style="text-align: center;">4004</p> <p>REPLACES MITSUBISHI MD314583 BOSCH 0986JG1012</p>
	<p style="text-align: center;">4005</p> <p>REPLACES MITSUBISHI MD314582 BOSCH 0986JG1013</p>





	<p style="text-align: center;">4006M</p> <p>REPLACES HANSHIN DSC-550 FORD FPY2-10-10X, FPY2-18-100, FPY2-18-10X MAZDA FP39-18-10XC, FP39-18-10XB FP39-18-10XD</p>
	<p style="text-align: center;">4007M</p> <p>REPLACES TOYOTA 90919-02226, 90919-02217, 90080-19008 90919-02218, 90919-02220, 90919-02219 90080-19007</p>
	<p style="text-align: center;">4008M</p> <p>REPLACES TOYOTA 90919-02224, 94856805</p>
	<p style="text-align: center;">4009</p> <p>REPLACES KIA KK-348-18-33X, 5WY2809A</p>
	<p style="text-align: center;">4010M</p> <p>REPLACES HANSHIN DSC-550 FORD FPY2-10-10X, FPY2-18-100, FPY2-18-10X MAZDA FP39-18-10XC, FP39-18-10XB, FPY1-18-10X FP39-18-10XD</p>

	<p style="text-align: center;">4011</p> <p>REPLACES KIA OK30E-18-10X</p>
	<p style="text-align: center;">4012</p> <p>REPLACES KIA OK9BV-18-10X</p>
	<p style="text-align: center;">4013</p> <p>REPLACES KIA OK30A-18-10X</p>
	<p style="text-align: center;">4014</p> <p>REPLACES KIA 27301-22600</p>
	<p style="text-align: center;">4015</p> <p>REPLACES KIA 27301-02700, 27301-02710</p>



	<p style="text-align: center;">4016</p> <p>REPLACES KIA 27301-02600, 27301-02620</p>
	<p style="text-align: center;">4017</p> <p>REPLACES KIA 27301-26600</p>
	<p style="text-align: center;">4018</p> <p>REPLACES KIA 27301-23700</p>
	<p style="text-align: center;">4019</p> <p>REPLACES KIA 27301-37100</p>

	<p style="text-align: center;">8001M</p> <p>REPLACES</p> <p>DAEWOO 88921374, 96350585, E586A, J-004B</p> <p>GM 10450424, 10490192, 1104038</p> <p>ISUZU 8-01104-038-0</p> <p>OPEL 1208051</p>
	<p style="text-align: center;">8002</p> <p>REPLACES</p> <p>DAEWOO 96253555, 93363483</p> <p>DELPHI 19005236, 19005265</p> <p>ISUZU 8-01104-039-0, 25182496</p> <p>SUZUKI 33410-84Z00</p>
	<p style="text-align: center;">8003M</p> <p>REPLACES</p> <p>VAUXHALL 10457075</p> <p>OPEL 1208063</p> <p>GM 10457075, 1103905, 1103872 D553, DR44</p>
	<p style="text-align: center;">8004M</p> <p>REPLACES</p> <p>VW/SEAT/SKODA 032 905 106, 032 905 106B</p> <p>FORD 7053859, 95WF-12029-BA</p> <p>BOSCH 0 221 603 010</p>
	<p style="text-align: center;">8005</p> <p>REPLACES</p> <p>CHRYSLER 04557468, 04609080, 04671025 4557468, 4609080, 4671025</p> <p>MITSUBISHI M04557468</p>

	<p style="text-align: center;">8006</p> <p>REPLACES</p> <p>FIAT/LANCIA 9607405480, 9622889780</p> <p>CITROEN 597048, 597060, 96074054</p> <p>PEUGEOT 597048, 597070</p> <p>BOSCH 0 221 503 025, 0 221 503 007</p>
	<p style="text-align: center;">8007</p> <p>REPLACES</p> <p>MOTOROLA 01R4304R01</p> <p>MARSHALL ME85-01</p>
	<p style="text-align: center;">8008</p> <p>REPLACES</p> <p>MAZDA 1E05-18-100, 1E05-18-100A, ZZM0-18-100, FSD7-18-100</p> <p>FORD 8SF-12029-A1A, 88F-12029-A1A, 88SF-12029-A1A, 88SF-12029-A2A 928F-12029-CA, E8TF-12029-AA, E8TZ-12029-A, E9TF-12029-AA F1VU-12029-A1A, F1VU-12029-A2A, F1VU-12029-A, F5LU-12029-AA F5LY-12029-A, F50U-12029-AA, F50Y-12029-A, F50Y-12029-B F5RZ-12029-C, F37U-12029-AA, F37Z-12029-A, EE-03A, 19017116</p> <p>LUCAS DMB750, DMB751. DENSO 0297006700</p>
	<p style="text-align: center;">8009</p> <p>REPLACES</p> <p>MAZDA 1E04-18-10X, 1E05-18-100B 1F20-18-100, YF09-18-10X</p> <p>FORD 988F-12029-AB, 988F-12029-AC, 988F-12029-AD 1067601, 1075786, 1130402, 1317972, 1111213 1319929, 1119835, 1619343 1S7G-12029-AB, XS8Z-12029-AA, YM2F-12024-AC YM2F-12024-AD, 1S7Z-12029-AA, 1S7G-12029-AC</p>
	<p style="text-align: center;">8010</p> <p>REPLACES</p> <p>CHRYSLER 05269670, 5269670, 56032521, 56032521AB</p> <p>MITSUBISHI M05269670</p>

	<p style="text-align: center;">8011</p> <p>REPLACES MAZDA L813-18-100</p>
	<p style="text-align: center;">8012</p> <p>REPLACES NISSAN 22448-00QAD RENAULT 82 00 051 128, 82 00 084 401 BOSCH 0 986 221 036 PEUGEOT 597083 PROTON 82 00 051 128</p>
	<p style="text-align: center;">8013</p> <p>REPLACES ALFA ROMEO 60558152, 60586072, 60809606, 7648797, 76487970 CITROEN/PEUGEOT 597053 BOSCH 0 221 503 407 FERRARI 134386 KIA 0K011-18-100, PW811201 HONDA 30520-PDF-E00 RENAULT 60 00 581 617 ROVER ERR6045 VW 048 905 1051</p>
	<p style="text-align: center;">8014M</p> <p>REPLACES VW 06A 905 097, 06A 905 104</p>
	<p style="text-align: center;">8015</p> <p>REPLACES FORD 1350567, 1350562, 1458400, 1459278, 30731416 1727629, 1754514, 30731416, C401-18-100 4M5G-12029-ZB, 4M5G-12029-ZA 4S7G-12029-AA, 4S7G-12029-AB CM5G-12029-FA, CM5G-12029-FB BOSCH 0 221 503 487, 0221 503 485</p>

	<p style="text-align: center;">8016</p> <p>REPLACES CUMMINS 3937301</p>
	<p style="text-align: center;">8017</p> <p>REPLACES GM/DELPHI 19005270 DAEWOO 9015239</p>
	<p style="text-align: center;">8018</p> <p>REPLACES FORD 988F-12029BA, 988F-12029AD, 1S7G-12029AC YM2F-12029AB BOSCH 0221 503 490 MAZDA LF01-18-100, LF01-18-100A, LF20-18-100</p>
	<p style="text-align: center;">8019</p> <p>REPLACES NISSAN 22448-00QAF RENAULT 8200 360 911, 8200 702 693, 8200 713 680</p>
	<p style="text-align: center;">8020</p> <p>REPLACES VW/SEAT/SKODA 032 905 106, 032 905 106B FORD 7053859, 95WF-12029-BA BOSCH 0 221 603 010</p>

	8021
	REPLACES FORD 1F2U-12029-AC, DG485, 5F2Z-12029-AD AU2-12029-A
	8022
	REPLACES BOSCH F01R 00A 025, 0221 503 465