



REPLACEMENT FOR

COASTER BB10

REPLACEMENT FOR

COASTER BB20

REPLACEMENT FOR

COASTER BB42 '93-'99

212-1554

CORNER LAMP
R 81511-36130
L 81521-36080
200PCS
4CFT



212-1944

TAIL LAMP
R 81550-39146
L 81560-39145
10PCS CFT

00-212-1944
50PCS 2.7CFT



**212-1627-V1 (12V)
V2 (24V)**

CORNER LAMP
R 81510-39465
L 81520-39465
20PCS 2.2CFT
00-212-1627 LENS
100PCS 4.2CFT



212-11A6-RD

HEAD LAMP
RD:
R 81110-36170
L 81150-36150
PCS CFT

R 81110-36290
L 81150-36260



H4/H3

TBA

212-1577-CY

CORNER LAMP
R 81510-36270
L 81520-36210
20PCS 6.67CFT




212-1577-Y

CORNER LAMP
R 81510-36280
L 81520-36220
20PCS 6.67CFT



212-1207

LIGHT CASE
R 53131-39115
L 53132-39115
12PCS 4.39CFT



212-1230

LIGHT CASE
R 53131-36010
L 53132-36010
5PCS 1CFT



212-1702

LIGHT HOUSING
R 81110-80226
L 81150-80223
PCS CFT



212-1980-2A

TAIL LAMP
R 81550-36260
L 81560-36260
6PCS 3.5CFT



**212-1930-V2 (24V)
V1 (12V)
U (W/O)**

TAIL LAMP
R 81550-39705
L 81560-39605
R 81550-39715
L 81560-39675
10PCS 3.75CFT



212-19L2-A

TAIL LAMP
R 81555-36420
L 81150-36260
PCS
CFT



'03

P21W/P21W/P21/5W/W5W

TBA

TOYOTA